

Installation Procedure

Tyros OS Upgrade 1.40 via Floppy Disk


To start: Prepare fourteen (14) Floppy Disks (2HD MS-DOS format), then copy the following files to disks one by one and label the file name on each disk.

Program Files	
MINSTALL.PRГ	MANPROG7.prg
MANPROG1.prg	MANPROG8.prg
MANPROG2.prg	MANPROG9.prg
MANPROG3.prg	MANPROG10.prg
MANPROG4.prg	MANPROG11.prg
MANPROG5.prg	MANPROG12.prg

1. Press the [POWER] switch while holding the STYLE CONTROL [START/STOP] button. Do not turn off until installation is completed. If Tyros is accidentally turned off during installation, please see the [Troubleshooting](#).
2. The following screen appears.



3. Insert the Floppy Disk [MINSTALL.prg].



4. Tyros automatically starts loading data from the floppy disk.



5. Screen below appears when data check begins.



6. When above message appears eject floppy disk [MINSTALL.prg].
7. The screen below asks to insert next DISK.

8. To check that the version has been updated, proceed as follows:
 - a. Switch Tyros power back on
 - b. Select FUNCTION -> UTILITY -> OWNER to open the OWNER window
 - c. Hold down the OWNER NAME button for 5 seconds, until the new version information appears
 - d. Confirm the version number is the one which you installed



Troubleshooting

If Tyros is accidentally turned off during installation, press the [POWER] switch of Tyros again while holding the STYLE CONTROL [START/STOP] button so that "Program install mode" appears on the LCD, and follow the installation procedure explained here again.

Tyros OS Version Upgrade List

The following problems are solved on Version 1.20 (revisions from Version 1.10):

Function	Problem
Vocal Harmony	When the Vocal Harmony is turned on or off, the vocal sound is interrupted. The interruption time is decreased on the new version.
One Touch Setting	When the One Touch Setting is selected after choosing a style on Floppy Disk or Hard Disk, Split Points and Fingering type reset to default value.
Registration Memory	When a different song is selected by the Registration Memory, the Chord Detect and VH Song Track settings aren't set correctly.
Song Creator	If a song contains System Exclusive Message of more than 128 bytes and this song is edited by Song Creator, this song can't be played on Tyros.
USB (for HDD Users)	The new file transfer function for Hard Disk is added on the new version. This new function provides approximately 1.6Mbit/sec of average transfer speed between PC and Hard Disk on the Tyros. (The speed depends on the circumstances such as PC performance, file size and so on.) Please refer to the "USB-Storage Mode (HDD) Operation Manual."